CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Kincaid		Date:	03/16/23	
Impoundment Name:	Ash Pond		· Time:		
IEPA Number:	W0218140002-01		Inspector(s):	D. Huben	
Sky: Cloudy Temp.:	45°F Pr	recip. (last 48 hrs):	0.00	Pool Elev.:	-14"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		NO			12	CTIO	N
			DESCRIPTION		MONITOR	INVESTIGATE	SENT TO
CREST General Con	dition.	Good	/ Fair / Poor Repairs:	Date:			
Cracking		V	3				
Settlement		V					-
Erosion Rills		V					
Animal Burrows		V					-
Misalignment		V	·				
Vegetation (greater than 12")		V					
UPSTREAM EMBANKMENT General Cor	dition:	Good	Fair / Poor Repairs:	Date:			-
Cracking		V					┼
Sloughing / Bulging		V					
Seepage		V					-
Sink Holes		V					
Animal Burrows		V	55 g				
Erosion Rills		V		<u> </u>			-
Slope Protection / Rip Rap		V	12				-
Vegetation (greater than 12")		K					-
DOWNSTREAM EMBANKMENT General Cor	dition	Good	/ Fair / Poor Repairs:	Date:			_
Cracking		V					
Sloughing / Bulging		V					-
Seepage		V					
Sink Holes		V		and the second s			
Sand Boils (indicate if flowing and color)		V			V		-
Animal Burrows	V		Finding/ Filling				-
Erosion Rills		V	· U	The state of the s			-
Vegetation (greater than 12")		V					-
SPILLWAY(S) General Cor	dition	Good	Fair / Poor Repairs:	Date:			-
Actively Flowing (provide depth)		V					
Obstructions Present		V					-
Seepage		V					-
Sand Boils (indicate if flowing and color)		V					-
Erosion Rills		V	94	*			