CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station	Kincaid		Date:	11/29/	23
Impoundment Name	Ash Pond	_	Time:	9:30	AM
IEPA Number	W0218140002-01	_	Inspector(s):	12. Hu	bur
Sky: Croudy Temp.	47°F	Precip. (last 48 hrs):	0,00	Pool	Elev.: -12 15

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		NO	DESCRIPTION		ACTION			
					MONITOR	INVESTIGATE	SENT TO DSM	
CREST General Con-	dition.	Good	Fair / Poor	Repairs:	Date:			
Cracking		V						
Settlement		V						
Erosion Rills		V						
Animal Burrows		V						
Misalignment		V			4			
Vegetation (greater than 12")		2						
UPSTREAM EMBANKMENT General Con-	dition	Good	Fair / Poor	Repairs:	Date:			
Cracking		V						
Sloughing / Bulging		V						
Seepage		V						
Sink Holes		V						
Animal Burrows		V						
Erosion Rills		V						
Slope Protection / Rip Rap		1						
Vegetation (greater than 12")		V	\					
DOWNSTREAM EMBANKMENT General Cond	dition:	Good	Fair / Poor	Repairs:	Date:			
Cracking		V						
Sloughing / Bulging		V						
Seepage		V						
Sink Holes		V						
Sand Boils (indicate if flowing and color)		V						
Animal Burrows			Finsing/	FILLIAM,		V		
Erosion Rills		V		0				
Vegetation (greater than 12")		X						
SPILLWAY(S) General Cond	dition:	Good	/ Fair / Poor	Repairs:	Date:			
Actively Flowing (provide depth)		V						
Obstructions Present		V						
Seepage		V						
Sand Boils (indicate if flowing and color)		V						
Erosion Rills		V						