CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

	Station:	Newtor	1	Date:	5/22/2024	
Impoundn	nent Name:	Primarry Ash	Pond	Time:	7:30 AM	
IEPA Number: W0780700001			01-01	Inspector(s):	Terry Hanratty	
Sky: Cloudy	Temp.:	68	Precip. (last 48 hrs):	0.3"	Pool Elev.:	534.5

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM						ACTION			
		YES	S NO DESCRIPTION			MONITOR	INVESTIGATE	SENT TO DSM	
CREST	General Cond	ition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking			Х						
Settlement			Х						
Erosion Rills			Х						
Animal Burrows			Х						
Misalignment			Х						
Vegetation (greater than 12")			Х						
UPSTREAM EMBANKMENT	ition:	Good	/ Fair / Poor	Repairs:	Date:				
Cracking			Х						
Sloughing / Bulging		Х		Minor sloghing c	n south side-cont	inuing to monitor	Х		
Seepage			Х						
Sink Holes			Х						
Animal Burrows			Х						
Erosion Rills			Х						
Slope Protection / Rip Rap			Х						
Vegetation (greater than 12")			Х						
DOWNSTREAM EMBANKMENT General Conditi			Good	/ Fair / Poor	Repairs:	Date:			
Cracking			Х						
Sloughing / Bulging			Х						
Seepage			Х						
Sink Holes			Х						
Sand Boils (indicate if flowing and color)			Х						
Animal Burrows			Х						
Erosion Rills			Х						
Vegetation (greater than 12")			Х						
SPILLWAY(S)	General Cond	ition:	Good	/ Fair / Poor	Repairs:	Date:			
Actively Flowing (provide depth)			Х	Remo	ved 1 stop log 11,	/16/22			
Obstructions Present			Х						
Seepage			Х						
Sand Boils (indicate if flowing and color)			Х						
Erosion Rills			Х						