## CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Newton	Date: _	6/26/2024
Impoundment Name:	Primarry Ash Pond	Time:	2:30 PM
IEPA Number:	W0780700001-01	Inspector(s):	Terry Hanratty

Precip. (last 48 hrs):

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach

0.75"

**Pool Elev.:** 

534

additional sheets as necessary. Circle General Condition for each section.

80

Temp.:

Sky: Cloudy

additional sheets as necessary. Circle General Conc  ITEM		101 Ca			ACTION		
		NO			MONITOR	INVESTIGATE	SENT TO DSM
<b>CREST</b> Genera	al Condition:	Good	Fair / Poor Repairs:	Date:			
Cracking		Χ					
Settlement		Χ					
Erosion Rills		Χ					
Animal Burrows		Χ					
Misalignment		Χ					
Vegetation (greater than 12")		Χ	Blankenship mowed the week of 6	5-24-24			
UPSTREAM EMBANKMENT General	al Condition:	Good	Fair / Poor Repairs:	Date:			
Cracking		Χ					
Sloughing / Bulging			Minor sloghing on south side-continuin	g to monitor	Χ		
Seepage		Χ					
Sink Holes		Χ					
Animal Burrows		Χ					
Erosion Rills		Χ					
Slope Protection / Rip Rap		Х					
Vegetation (greater than 12")		Х	Blankenship mowed the week of 6	5-24-24			
DOWNSTREAM EMBANKMENT General	al Condition:	Good	Fair / Poor Repairs:	Date:			
Cracking		Χ					
Sloughing / Bulging		Х					
Seepage		Χ					
Sink Holes		Х					
Sand Boils (indicate if flowing and color)		Χ					
Animal Burrows		Χ					
Erosion Rills		Χ					
Vegetation (greater than 12")		Χ	Blankenship mowed the week of 6	5-24-24			
SPILLWAY(S) General	al Condition:	Good	Fair / Poor Repairs:	Date:			
Actively Flowing (provide depth)		Χ	Removed 1 stop log 11/16/2	.2			
Obstructions Present		Χ					
Seepage		Х					
Sand Boils (indicate if flowing and color)		Χ					
Erosion Rills		Χ					